



**THIS NOTICE IS FOR THE INFORMATION OF
SHIP'S MASTERS AND OTHERS CONCERNED**

FREMANTLE PORTS NOTICE TO MARINERS 1/2007

**FREMANTLE PORT
KWINANA & COCKBURN SOUND – ISOLATED DANGER
MARK - Reposition**

Former Notice – FPA NTM 20(T)2006 is cancelled

The isolated danger mark buoy with topmark deployed as per FPA NTM 20(T)/2006 has now been relocated to its permanent position as follows:

Position (WGS84)

32-12.054 S 115-46.230 E

Marker Buoy & Light Characteristics

ISDM, Fl (2) 8s (0.5s on, 1.0s off, 0.5s on
then 6.0s off)



Mariners are advised to navigate with caution in this area.

Charts Affected

RAN: Aus 114 - Aus 117

DPI: WA 001

Capt E J Atkinson
Harbour Master
Fremantle Ports
12 January, 2007