



**THIS NOTICE IS FOR THE INFORMATION OF
SHIP'S MASTERS AND OTHERS CONCERNED**

**FREMANTLE PORTS NOTICE TO MARINERS
21/2006**

**FREMANTLE PORT
INNER HARBOUR – NORTH & SOUTH MOLE HEADLANDS –
Lighthouse Light Characteristic Modifications**

Former Notice – FPA NTM 18/2006 is cancelled.

Date – On 17 November, 2006.

List of Lights Vol K/2006/7 – 1764 (North Mole. Head) & 1765 (S Mole. Head)

Commencing on 17 November 2006, the light characteristics of both North and South Mole headland lights will be changed as indicated below:

North Mole (Vol K 1764)

- a. Existing Iso.R.2s 15m 11M – removed and replaced with VQ.R. 15m 6M (0.2 seconds on, 0.3 seconds off); and
- b. Existing VQ.R. 16m 6M – removed (not replaced).

South Mole (Vol K 1765)

- a. Existing Iso.G.2s 15m 11M – removed and replaced with VQ.G. 15m 6M (0.2 seconds on, 0.3 seconds off).

Mariners are advised to navigate with caution.

Charts Affected

RAN: Aus 113 - Aus 117

DPI: WA 001

Capt E J Atkinson
Harbour Master
Fremantle Ports
17 November, 2006