




**HIS NOTICE IS FOR THE INFORMATION OF SHIP'S
MASTERS AND OTHERS CONCERNED**

**FREMANTLE PORTS NOTICE TO MARINERS
2(T)/2020**

**FREMANTLE PORT
Hall Bank Beacon**

Mariners are advised that the Hall Bank Beacon has had the loose concrete removed and a temporary light fitted.

Light Characteristics
Occ.Y.3s



Hall Bank Beacon - *damaged.*

Mariners are advised to navigate with caution.

Charts Temporarily Affected
RAN: Aus 112 and Aus 113 ,
DoT: WA 001

Capt David Heppingstone
Harbour Master
Fremantle Ports
20th March, 2020