



**THIS NOTICE IS FOR THE INFORMATION OF
SHIP'S MASTERS AND OTHERS CONCERNED**

**FREMANTLE PORTS NOTICE TO MARINERS
25/2006**

**FREMANTLE PORT
COCKBURN SOUND – MOORING BUOYS
Replaced & Repositioned**

Adsteam's two (2) permanent mooring buoys located approximately 1010 metres and 1250 metres NE by N of Colpoys Point, Garden Island, respectively have been replaced by larger, more visible buoys. Coordinates have also been updated as:

<i>Position (WGS84)</i>	<i>Buoy Type</i>
32-12.9682 S 115-42.4301 E	Barrel
32-13.1487 S 115-42.4182 E	Barrel



Mooring Buoy – North



Mooring Buoy - South

Note that both buoys are currently **unlit** pending measures to prevent theft/damage of the light mechanisms. Furthermore, adjacent to each buoy will be two small floats that are affixed to the buoy's recovery line(s).

Mariners are advised to navigate with caution in these areas.

Charts Affected

RAN: Aus 111 - Aus 114 - Aus 117

DPI: WA 001

Capt E J Atkinson
Harbour Master
Fremantle Ports
27 December, 2006