



**THIS NOTICE IS FOR THE INFORMATION OF
SHIP'S MASTERS AND OTHERS CONCERNED**

**FREMANTLE PORTS NOTICE TO MARINERS
6/2008**

**FREMANTLE PORT
INNER HARBOUR – Current Meter Repositioned**

Former Notice – FPA NTM 9(T)2007 is cancelled
Former Notice – FPA NTM 14(P)2007 is cancelled
Former Notice – FPA NTM 23(T)2007 is cancelled

Mariners are advised that the Inner Harbour Current Meter that was temporarily located approximately 25 metres north east of White's Landing, has now been relocated back to its charted position being 40 metres west of the Fremantle Railway Bridge.

Former Position (WGS84)
32-03.001 S 115-44.396 E

Marker Buoy & Light Characteristics
Special Spar, Fl.Y.5s

New Position (WGS84)
32-02.459 S 115-45.238 E

Marker Buoy & Light Characteristics
Special Spar, Fl.Y.5s

Mariners are advised to navigate with caution in this area.

Charts Temporarily Affected
RAN: Aus 113
DPI: WA 001

Capt E J Atkinson
Harbour Master
Fremantle Ports
15 April, 2008

