

PORT OF FREMANTLE

NAVIGATIONAL WARNING

Number 11 / 2022

Email movements@fremantleports.com.au

Date of issue: 11/08/2022

Date of effect: 11/08/2022

Date of cancellation: TBC

Charts affected: AUS 112

NAVIGATION HAZARD

Fremantle Fairway landfall Buoy in position 31 57.15 S, 115 38.83 E (LFL.10s, Racon V) has been damaged by recent bad weather. A temporary replacement buoy (See Below) has been placed in this location until repairs are completed. The temporary light characteristics are LFL 10s with an nominal range of 6.5Nm.

Mariners are advised to use other means to verify landfall and to exercise caution while navigating in this area.

