



PORT OF FREMANTLE

NAVIGATIONAL WARNING

Number 20/2021

Email movements@fremantleports.com.au

Date of issue: 17th May 2021

Date of effect: 17th May 2021

Date of cancellation TBA

Charts affected: AUS 112/ 113

HALL BANK Temporary Buoy - Flash Characteristic

As of 17th May 2021, the temporary buoy at Hall Bank as changed to Flashing Quick Yellow (Q.Y)

Position approx. 32° 01.84' South, 115° 43.73' East.

Mariners are advised to navigate with caution.

Harbour Master's Office
Fremantle Ports