



**THIS NOTICE IS FOR THE INFORMATION OF  
SHIP'S MASTERS AND OTHERS CONCERNED**

**FREMANTLE PORTS NOTICE TO MARINERS  
5/2008**

**FREMANTLE PORT  
ROUS HEAD – Power Generator (CETO) Obstruction and  
Navigational Marks**

*Former Notice* – FPA NTM 2(T)2007 is cancelled

*Former Notice* – FPA NTM 3(T)2007 is cancelled

Mariners are advised that the previous special buoys as promulgated under FPA NTM 3(T)/2007 have been repositioned.

A subsurface power generating structure/CETO has been established with an exclusion zone delimited by four (4) cardinal marks (similar to the West Cardinal mark pictured) with positions as indicated below. Additionally, a wave rider buoy exists within the area enclosed by the cardinal marks.

<i>Position (WGS84)</i>	<i>Marker Buoy &amp; Light Characteristics</i>
32-02.7200 S 115-43.7283 E	North Cardinal, Q 2M
32-02.8283 S 115-43.7283 E	South Cardinal, Q(6) + LFI.15s 2M
32-02.7733 S 115-43.7917 E	East Cardinal, Q(3).10s 2M
32-02.7733 S 115-43.6650 E	West Cardinal, Q(9).15s 2M
32-02.7640 S 115-43.7150 E	Spherical Buoy, Q(5)Y.20s 2M

A submerged pipeline also connects the CETO to the shore. The pipeline coordinates at the location of exit from the seabed to the shore are 32-02.755 S ; 115-43.917 E (WGS84).

Mariners are advised to navigate with caution in this area especially in the vicinity around Eleanor Rocks to the north of the CETO deployment.

**Charts Temporarily Affected**

**RAN: Aus 112 - Aus 113**

**DPI: WA 001**

Capt E J Atkinson  
Harbour Master  
Fremantle Ports  
15 April, 2008

