



**THIS NOTICE IS FOR THE INFORMATION OF
SHIP'S MASTERS AND OTHERS CONCERNED**

**FREMANTLE PORTS NOTICE TO MARINERS
1(T)/2018**

**FREMANTLE PORT
INNER HARBOUR – NORTH & VICTORIA QUAYS -
Berth Depths**

Due to the accretion and movement of silt alongside Fremantle Port Inner Harbour berths, the declared depths (reduced to Fremantle LAT) of each berth have been revised. Accretion has typically occurred within, but is not limited to, a distance of less than 20m from the face of the berth.

North Quay			Victoria Quay		
Berth	Declared Depth	Pier Markings	Berth	Declared Depth	Pier Markings
1	10.8	230W to 210 W	A	<i>not surveyed</i>	
2	11.0	210W to 120W	B	<i>not surveyed</i>	
4	14.5	50W to 20W	C	10.5 *	20W to 00E
5	14.5	20W to 20E	D	10.5 *	00E to 40E
6	14.5	20E to 60E	E	10.5 *	40E to 100E
7	14.5	60E to 110E	F	10.8	100E to 150E
8	14.5 *	110E to 150E	G	10.5 *	150E to 180E
9	14.5 *	150E to 200E	H	10.5 *	180E to 240E
10	14.2 *	200E to 216E			
11	10.7	300E to 350E			
12	10.7	350E to 380E			

* Denotes a change since last published DECLARED DEPTHS (2(T)/2017)

Maximum draft of vessels using Inner Harbour berths **must be obtained** by contacting the Harbour Master's office.

Mariners are advised to navigate with caution.

Charts Temporarily Affected

RAN: Aus 112 - Aus 113 ; DPI: WA 001

Capt A J Gray
Harbour Master
Fremantle Ports
12 March, 2018