



**THIS NOTICE IS FOR THE INFORMATION OF
SHIP'S MASTERS AND OTHERS CONCERNED**

**FREMANTLE PORTS NOTICE TO MARINERS
12/2011**

**FREMANTLE PORT
Fairway Landfall Buoy - RACON ID Change**

Former Notice – FPA NTM 15/2008 is cancelled

The morse identification letter assigned to the Fairway Landfall Buoy RACON has been changed to the morse identification letter **Victor (V)**.

Additionally, the Fairway Landfall Buoy has been fitted with AIS (MMSI 995031029).

Admiralty List of Lights and Fog Signals Vol K (NP83) International Number 1763.8 refers.

Mariners are advised to navigate with caution.

Charts Affected

RAN: Aus 112, Aus 754

DPI: WA 001

Capt A J M Gray
Harbour Master
Fremantle Ports
27th June, 2011