



**THIS NOTICE IS FOR THE INFORMATION OF  
SHIP'S MASTERS AND OTHERS CONCERNED**

**FREMANTLE PORTS NOTICE TO MARINERS  
2(T)/2017**

**FREMANTLE PORT  
INNER HARBOUR – NORTH & VICTORIA QUAYS -  
Berth Depths**

*Former Notice – FPA NTM 1(T)/2017 is cancelled*

Due to the accretion and movement of silt alongside Fremantle Port Inner Harbour berths, the declared depths (reduced to Fremantle LAT) of each berth have been revised. Accretion has typically occurred within, but is not limited to, a distance of less than 20m from the face of the berth.

North Quay		Victoria Quay	
Berth	Declared Depth	Berth	Declared Depth
1	10.8	A	*
2	11.0	B	*
4	14.5	C	10.7
5	14.5	D	10.9
6	14.5	E	10.8
7	14.5	F	10.8
8	14.3**	G	10.0
9	14.0	H	10.0
10	13.7		
11	10.7		
12	10.7		

\* Berths A & B (Victoria Quay) are no longer used for commercial shipping.

\*\* Eastern extent of Berth 8 is adjacent to pier 160E.

Maximum draft of vessels using inner harbour berths **must be obtained** by contacting the Harbour Master's office.

Mariners are advised to navigate with caution.

**Charts Temporarily Affected**  
**RAN: Aus 112 - Aus 113 ; DPI: WA 001**

Capt A J Gray  
Harbour Master  
Fremantle Ports  
24 January, 2017